

Uranium Mining in Texas: Why Is It Done That Way?

Table 2. Radium levels of all test wells from all analyses

Test	Radium	RBLB 1,3,4,5 (PCI/l)	PTW 1-6 (PCI/l)	PTW 7-14 (PCI/l)	ALL WELLS (PCI/l)
First Test	Average	408	138	475	334
	High	1091	357	1684	1684
	Low	37	17	10	10
	Stand. Dev.	480	138	561	426
Second Test	Average	627	185	537	421
	High	1210	549	2000	2000
	Low	87	17	65	17
	Stand. Dev.	477	205	653	491
Third Test	Average	692	227	465	419
	High	1500	830	1590	1590
	Low	85	10	63	10
	Stand. Dev.	597	314	509	468